



## Machine Record card

1 of 4  
Apr 16, 2020  
12:42:11 PM

LEAN 2011

|                              |                                                                     |                      |              |
|------------------------------|---------------------------------------------------------------------|----------------------|--------------|
| <b>s/n</b>                   | L017D796                                                            | Work nr.:            | L017D796     |
| <b>Name</b>                  | SANDVIK LH517i 796                                                  |                      |              |
| <b>Delivered to Customer</b> | Sandvik Mining<br>SANDVIK MINING AND CONSTRUCTION AUSTRALIA PTY LTD |                      |              |
| <b>Delivery date</b>         | 27.04.2020                                                          | <b>Order no</b>      | <b>65902</b> |
|                              |                                                                     | <b>Cust order no</b> | R359851      |

| Item | Name | Techn. descr. | Serial / Manuf. nr. |
|------|------|---------------|---------------------|
|------|------|---------------|---------------------|

### Framework

|            |                  |                                 |                                                                                         |
|------------|------------------|---------------------------------|-----------------------------------------------------------------------------------------|
| BG01277140 | BUSHINGS, BUCKET | SANDVIK BG01277140 8.6 m3       | 200134 LH238672 Y:20/3<br>S:747 ,size: 8.6 m3                                           |
| BG00748000 | CABIN ASSEMBLY   | SANDVIK BG00748000 LH514, LH517 | MR200538 LH240916 20/3 200<br>ROPS: JP200538 LH240916 2002<br>120<br>I/O mod.: 21069021 |

### Powertrain

|            |                  |                    |                        |                                        |
|------------|------------------|--------------------|------------------------|----------------------------------------|
| BG00854407 | ENGINE           | Volvo              | TAD1382VE 315kW Stage5 | 2013971041<br>CAT: 016077886<br>364984 |
| BG00779735 | RADIATOR         | SANDVIK BG00779735 |                        | 256972-1-6 01-20                       |
| BG00818653 | AXLE             | SANDVIK BG00818653 |                        | 796109 F                               |
| BG00818653 | AXLE             | SANDVIK BG00818653 |                        | 798086 R                               |
| BG00764470 | TRANSMISSION     | SANDVIK BG00764470 |                        | CBEA 137637                            |
| BG01259853 | TORQUE CONVERTER | SANDVIK BG01259853 |                        | CBEA909244                             |

**Postal Address:**  
Sandvik Mining and Construction Oy  
P.O. Box 434 (Vahdontie 19)  
FIN-20101 Turku  
FINLAND

Reg no 2.852  
VAT no FI0211600-7  
[www.miningandconstruction.sandvik.com](http://www.miningandconstruction.sandvik.com)

tel. +358 205 44 131  
fax. +358 205 44 130



## Machine Record card

2 of 4  
Apr 16, 2020  
12:42:11 PM

LEAN 2011

|                              |                                                                     |                      |                |
|------------------------------|---------------------------------------------------------------------|----------------------|----------------|
| <b>s/n</b>                   | L017D796                                                            | Work nr.:            | L017D796       |
| <b>Name</b>                  | SANDVIK LH517i 796                                                  |                      |                |
| <b>Delivered to Customer</b> | Sandvik Mining<br>SANDVIK MINING AND CONSTRUCTION AUSTRALIA PTY LTD |                      |                |
| <b>Delivery date</b>         | 27.04.2020                                                          | <b>Order no</b>      | <b>65902</b>   |
|                              |                                                                     | <b>Cust order no</b> | <b>R359851</b> |

| Item | Name | Techn. descr. | Serial / Manuf. nr. |
|------|------|---------------|---------------------|
|------|------|---------------|---------------------|

### Hydraulics

|            |                              |                                             |                                  |
|------------|------------------------------|---------------------------------------------|----------------------------------|
| BG00776817 | COOLER, OIL                  | SANDVIK BG00776817                          | <b>DLYSQ05U</b>                  |
| BG00776818 | COOLER, OIL                  | SANDVIK BG00776818                          | <b>A4106NFQ</b>                  |
| BG00840060 | CYLINDER, HYDRAULIC          | SANDVIK BG00840060                          | <b>616746</b>                    |
| 29613424   | CYLINDER, STEERING           | SANDVIK 29613424 125/90 x 475, T-0010       | <b>618463 Left</b>               |
| 29613424   | CYLINDER, STEERING           | SANDVIK 29613424 125/90 x 475, T-0010       | <b>618465 Right</b>              |
| BG00642817 | CYLINDER, TILT               | SANDVIK BG00642817 220/140x656, with sensor | <b>T-P-09-612863</b>             |
| BG00498986 | CYLINDER, LIFT               | SANDVIK BG00498986 180/110 x 1010           | <b>T-P-11-613661</b>             |
| BG00498986 | CYLINDER, LIFT               | SANDVIK BG00498986 180/110 x 1010           | <b>T-P-11-613664</b>             |
| BG00745868 | PUMP UNIT                    | SKF Lubrication systems SGH-50-6-8:1        | <b>04 20</b>                     |
| BG01048680 | HYDRAULIC MOTOR, VANE        | SANDVIK BG01048680                          | <b>20C17 210</b>                 |
| BG01105841 | HYDRAULIC PUMP, AXIAL PISTON | SANDVIK BG01105841                          | <b>63-20 0400020</b>             |
| BG01196567 | HYDRAULIC PUMP, AXIAL PISTON | SANDVIK BG01196567                          | <b>35602270</b>                  |
| 56043747   | PISTON PUMP                  | SANDVIK 56043747                            | <b>36145873</b>                  |
| BG00776977 | PUMP, PISTON                 | SANDVIK BG00776977                          | <b>36111625</b>                  |
| BG00776978 | PUMP, PISTON                 | SANDVIK BG00776978                          | <b>36158237</b>                  |
| BG01469692 | MANIFOLD, VALVE ASSEMBLY     | SANDVIK BG01469692                          | <b>V-50487-A 2/20</b>            |
| BG00195172 | VALVE ASSEMBLY               | SANDVIK BG00195172                          | <b>36/19</b>                     |
| 56047418   | VALVE, BRAKE                 | SANDVIK 56047418                            | <b>36/19</b>                     |
| BG00876460 | VALVE, BRAKE                 | SANDVIK BG00876460                          | <b>06 466 611 20M009</b>         |
| BG00712387 | VALVE, DIRECTIONAL           | SANDVIK BG00712387                          | <b>2002-3460702-002</b>          |
| BG00175261 | Accumulator                  | SANDVIK BG00175261                          | <b>01/20 6L 70Bar 1106079</b>    |
| BG00175264 | Accumulator                  | SANDVIK BG00175264                          | <b>03/20 6L 20Bar 1117508</b>    |
| BG01048550 | ACCUMULATOR, DIAPHRAGM       | SANDVIK BG01048550                          | <b>1,4L 07/19 5714667 14 bar</b> |
| BG00824168 | ACCUMULATOR,                 | SANDVIK BG00824168                          | <b>1114016 02/2020</b>           |

#### Postal Address:

Sandvik Mining and Construction Oy  
P.O. Box 434 (Vahdontie 19)  
FIN-20101 Turku  
FINLAND

Reg no 2.852  
VAT no FI0211600-7  
[www.miningandconstruction.sandvik.com](http://www.miningandconstruction.sandvik.com)

tel. +358 205 44 131  
fax. +358 205 44 130



## Machine Record card

3 of 4  
Apr 16, 2020  
12:42:11 PM

### LEAN 2011

|                              |                                                                     |                      |                |
|------------------------------|---------------------------------------------------------------------|----------------------|----------------|
| <b>s/n</b>                   | L017D796                                                            | Work nr.:            | L017D796       |
| <b>Name</b>                  | SANDVIK LH517i 796                                                  |                      |                |
| <b>Delivered to Customer</b> | Sandvik Mining<br>SANDVIK MINING AND CONSTRUCTION AUSTRALIA PTY LTD |                      |                |
| <b>Delivery date</b>         | 27.04.2020                                                          | <b>Order no</b>      | <b>65902</b>   |
|                              |                                                                     | <b>Cust order no</b> | <b>R359851</b> |

| Item | Name | Techn. descr. | Serial / Manuf. nr. |
|------|------|---------------|---------------------|
|------|------|---------------|---------------------|

PISTON

### Other

BG01012367 COMPRESSOR, A/C SANDVIK BG01012367 00065406901070

### Others

BG01331297 FIRE EXTINGUISHING SYSTEM SANDVIK BG01331297 65X12893 II840

### Main diagrams

| Item ID    | Item name            | Drawing    | Drawing revision |
|------------|----------------------|------------|------------------|
| BG00800405 | SCHEMATIC, HYDRAULIC | BG00800405 | C                |
| BG00860618 | SCHEMATIC, HYDRAULIC | BG00860618 | A                |
| BG00972672 |                      | BG00972672 | A                |
| BG01281493 |                      | BG01281493 | E                |

### Test drive

Date: Koeajo / KaV 16.04.2020

### Postal Address:

Sandvik Mining and Construction Oy  
P.O. Box 434 (Vahdontie 19)  
FIN-20101 Turku  
FINLAND

Reg no 2.852  
VAT no FI0211600-7  
www.miningandconstruction.sandvik.com

tel. +358 205 44 131  
fax. +358 205 44 130



## Machine Record card

4 of 4  
Apr 16, 2020  
12:42:11 PM

LEAN 2011

|                      |                                                   |               |              |
|----------------------|---------------------------------------------------|---------------|--------------|
| <b>s/n</b>           | L017D796                                          | Work nr.:     | L017D796     |
| <b>Name</b>          | SANDVIK LH517i 796                                |               |              |
| <b>Delivered to</b>  | Sandvik Mining                                    |               |              |
| <b>Customer</b>      | SANDVIK MINING AND CONSTRUCTION AUSTRALIA PTY LTD |               |              |
| <b>Delivery date</b> | 27.04.2020                                        | Order no      | <b>65902</b> |
|                      |                                                   | Cust order no | R359851      |

[-2-](#)

**Postal Address:**  
Sandvik Mining and Construction Oy  
P.O. Box 434 (Vahdontie 19)  
FIN-20101 Turku  
FINLAND

Reg no 2.852  
VAT no FI0211600-7  
[www.miningandconstruction.sandvik.com](http://www.miningandconstruction.sandvik.com)

tel. +358 205 44 131  
fax. +358 205 44 130