

### INSPECTION DETAILS

<b>Date:</b> 02/06/2022	<b>Reported By:</b> Michael
<b>Report No:</b> WPINSP144	

### MACHINE INFORMATION

<b>Serial Number:</b> JNW000214	<b>Quantity:</b> 1
<b>Machine Type:</b> Arcitulated Truck	<b>Hours:</b> 29811
<b>Make:</b> Caterpillar	<b>Model:</b> AD55B
<b>External Location:</b> NSW	
<b>Description:</b> Machine Build Date - 2011/02 Engine Build Date - 2010/08	

### MACHINE HISTORY

<b>Frame Hours:</b> 29811.8	<b>Engine:</b> 10000*
<b>Transmission:</b> 15632	<b>Torque Converter:</b> 7556
<b>Front Differential:</b> 15138	<b>Rear Differential:</b> 15138
<b>Pos 1 W/End:</b> 5897	<b>Pos 2 W/End:</b> 15138
<b>Pos 3 W/End:</b> 15138	<b>Pos 4 W/End:</b> 5897
<b>Steer Cyl R/H:</b> 5897	<b>Front Susp Cyl R/H:</b> 5897
<b>Front Susp Cyl L/H:</b> 5897	

### CUSTOMER NOTE

\* Engine requires repairs

### IMAGE(S)





